AST repair bladders inflate, keep

roof afloat

Pontoon liners (repair bladders) like this are for aboveground storage pontoon floating roof tanks.

They install inside the pontoon, are inflated to displace



product, then keep a roof afloat, declares the maker.

Most commonly these liners are used in a pontoon that has begun to leak — and can fill with tank product to cause a floating roof to sink with subsequent damage.

Pontoon liners comprise MesaThane for outstanding vapor sealing, flexibility, and hydrocarbon resistance. They keep a roof floating until repairs can be made, reduce risk of tank damage, and help prevent damage to a floating roof. These liners also help avoid environmental hazards or violations as they also prevent costly cleanup and decontamination procedures. More details are free. **Mesa Industries** 4141 Airport Road, Cincinnati OH 45226